


SS900 Three Phase Wiring Diagram



- ⊙ Main circuit terminals power
- Control loop
-  Please use shielded cable